

FIG.1




FIG.2

## INFORMATION PROCESSING APPARATUS




FIG. 3




FIG. 4






FIG.5



09845331.050101

FIG.6



F0T0S0" TEE54860

FIG.7




FIG.8






FIG.9



FOI050 FE54860




FIG.10



09045331.050101

FIG.11






FIG.13





FIG.14



09845331-050104


FIG.15

		STATUS OF POWER SOURCE	
		EXTERNAL POWER MODE	INTERNAL POWER SOURCE MODE
ERROR CONTENTS	ERROR IN SOFTWARE PROCESSING	L TIMES	M TIMES
	NO RESPONSE FROM THE OTHER PARTY	L TIMES	N TIMES

WHERE  $N < M < L$


09845331-050101

FIG.16



09845331.050101

FIG.17



09845331.050101



FIG.18

		STATUS OF POWER SOURCE	
		EXTERNAL POWER MODE	INTERNAL POWER SOURCE MODE
ERROR CONTENTS	ERROR IN SOFTWARE PROCESSING	t1	t2
	NO RESPONSE FROM THE OTHERPARTY	t2	t2

WHERE  $t1 < t2$

09845331.050101

FIG.19



09845331-050101  
TOTO50"TEES4860

FIG.20



09045331.050101